

Inspection

- Video
- Visual
- Written Inspection Reports
 - Insurance Claims
 - Real Estate Sales

Chimney

- Relining
- Sweeping
- Repair Existing
- Build New
- Fireplaces

Installation

- Wood/Pellet Stoves
- Wood/Pellet Inserts
- Walkways
- Retaining Walls
- Patios
- Veneer

- Power Washing
- Water Proofing



Artistic Masonry L.L.C.

54 Parker Road
New Boston, NH 03070-4200

Phone: 603.497.5493

Fax: 603.384.1072

E-mail: artisticmasonryllc@comcast.net



ARTISTIC MASONRY L.L.C.

24-Hour Emergency Service



Certification #6691













Certification #157156

**Woodburning
& Pellet
Specialist**

Visit us on the web:

www.ArtisticMasonryLLC.com

Every homeowner needs accurate information about his or her chimney's condition. In the past, the examination of the chimney interior involved either an ineffective flashlight and mirror or the expensive disassembly of part of the chimney to see problem areas. Now with the Chim-Scan® video inspection service, it is easy to obtain an accurate evaluation of your chimney's interior in a non-destructive way. Our video chimney inspection will be able to show you these unsafe chimney conditions, if they exist:

-  Improper new construction
-  Chimney fire damage
-  Improper prefab chimney connections
-  Deterioration from gas appliance connections
-  Cracks, even hairline cracks, in flue liners
-  Broken or missing tile liners and mortar joints
-  Deterioration from smoke shelf or damper
-  "Quick-fixed" thimble holes
-  Hidden breechings
-  Nests, limbs and other blockages

Insurance adjustors and home/fire inspectors and realtors depend on video inspections for accurate information. An examination soon after a mishap can determine the cause of damage: whit-ened mortar joints, blaze marks, missing mortar, cracks and discoloration in liners and buckling of steel liners are indications of sudden occurrence chimney damage.

Your inspection may provide several report formats: A written report on a chimney evaluation form, photo-graphs taken from the inspection monitor, or even a DVD recording of the inspection.

Non-Parged Fireplace Throat



Cracked Clay Chimney Liner



Disconnected Clay Liner



14.5 Level II Inspections. A Level II inspection is indicated when verification of the suitability of the chimney for new or changed conditions of service is needed or when a Level I inspection is not sufficient to determine the serviceability of the chimney.

14.5.1 Circumstances. A Level II inspection shall be conducted under the following circumstances:

- (1) Upon addition or removal of one or more connected appliances or upon replacement of an appliance with one or more dissimilar type, input rating, or efficiency, unless the last connected appliance is removed and chimney use will be discontinued
- (2) Prior to relining of a flue or replacement of flue lining
- (3) Upon sale or transfer of the property
- (4) After a building or chimney fire, weather or seismic event, or other incident likely to have caused damage to the chimney.

Artistic Masonry L.L.C.

54 Parker Road
New Boston, NH 03070-4200

Phone: 603.497.5493

Fax: 603.384.1072

E-mail: artisticmasonryllc@comcast.net